## Statement of corrective action following the USPH inspection below!

EUROPA  DETAILS OF INSPECTION VIOLATIONS			
NO. LOCATION CRITICAL	REF. POINTS DESCRIPTION		
1POTABLE WATER	06	0	No
THE METHOD BEING USED ON THE SHIP FOR ESCHERICI NOT AN ACCEPTED METHOD IN THE STANDARD METHOD EXAMINATION OF WATER AND WASTEWATER.		_	
Vessel will change to a approved system, which was recommended by USPH, probably to Milliflex 100 Test System from Millipore. We already got in touch with the company.			
2COMMENT	*	0	No
THIS VESSEL SHOULD DEVELOP A TIME MANAGEMENT I FOOD ITEMS ON THE BUFFET.	PLAN FO	R THE	
Vessel will immediately implement a time management plaitems displayed on the buffet!	an for all	food	
3VENTILATION	41	0	No
THE AIR HANDLING CONDENSATE DRAIN PANS WERE NOT ACCESSIBLE FOR INSPECTION AND CLEANING.			
The proposed way to solve the problem by installing a co the unit will be checked if it can be done!	ntrol wir	ndow into	)
4OPERATIONS-GENERAL	*	0	No
OVERALL, FOOD HANDLING, CLEANLINESS, AND GENER SERVICE OPERATIONS WERE EXCELLENT.	AL FOOI	)	
5FOOD SERVICE-GENERAL	33	0	No
SOME RECESSED TILE GROUTING WAS NOTED IN VARIO	US ARE	AS.	
Grouding will be filled in as soon as possible!			
6PASTRY AREA	27	0	No
GREASE RESIDUE WAS NOTED IN THE EXHAUST HOOD LEDGE LOCATED			

9/

ABOVE THE OVENS.

Cleaning plan has been established so this area will not be overlooked in the future.

## **7MAIN DISHWASHING**

22 0 No

THE RINSE TEMPERATURE OF THE DISHWASHER WAS 14° HIGHER THAN THE FINAL RINSE TEMPERATURE.

Repair crew has been ordered immediately from ashore who will solve the problem!

\* 0 No

IN DEVELOPING THE CORRECTIVE ACTION STATEMENT FOR THIS INSPECTION, CRITICAL-ITEM DEFICIENCIES (DESIGNATED WITH YES IN CRITICAL

COLUMN (WORTH 3 - 5 POINTS), WHETHER DEBITED OR NOT, SHOULD INCLUDE STANDARD OPERATING PROCEDURES AND MONITORING PROCEDURES IMPLEMENTED TO PREVENT THE RECURRENCE OF THE CRITICAL DEFICIENCY.

PREPARE CORRECTIVE ACTION STATEMENT AS A WORD PROCESSING OR SPREADSHEET FILE WHICH WILL BE SENT TO USPHS / VSP AS AN EMAIL MESSAGE ATTACHMENT. PLEASE EMAIL CORRECTIVE ACTION STATEMENT TO: VSP@CDC.GOV

USE EMAIL MESSAGE SUBJECT LINE: SHIP NAME - CAS - [INSERT INSPECTION DATE] .